DOCKET NO.: 289123US0RD PCT/hse

## IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

IN RE APPLICATION OF: Shinji SAITO, et al.

PATENT NO.: 7,592,641 GROUP: 2818

ISSUED: September 22, 2009 EXAMINER: Andy Huynh

FOR: SEMICONDUCTOR DEVICE, METHOD FOR FABRICATING AN ELECTRODE,

AND METHOD FOR MANUFACTURING A SEMICONDUCTOR DEVICE

## REQUEST FOR CERTIFICATE OF CORRECTION

DIRECTOR OF THE UNITED STATES PATENT AND TRADEMARK OFFICE ALEXANDRIA, VA 22313-1450

SIR:

The following is a Request for Certificate of Correction in Serial Number 10/574,850, now U.S. Patent Number 7,592,641.

In accordance with the provisions of Rule 322 of the Rules of Practice, which implement 35 USC 254, the U.S. Patent and Trademark Office is respectfully requested to issue a Certificate of Correction in the above-identified patent.

In light of the fact that the errors were the fault of the U.S. Patent and Trademark Office, no fees are required. The requested corrections are listed on FORM P.T.O. 1050.

Respectfully submitted,

OBLON, SPIVAK, McCLELLAND, MAIER & NEUSTADT, L.L.P. Norman F. Oblon

Vincent K. Shier, Ph.D. Registration No. 50,552

James D. Hamilton Registration No. 28,421

Customer Number

22850

Tel. (703) 413-3000 Fax. (703) 413-2220 (OSMMN 07/09) UNITED STATES PATENT AND TRADEMARK OFFICE

## **CERTIFICATE OF CORRECTION**

PATENT NO.:

7,592,641

DATED:

Sep. 22, 2009

INVENTOR(S):

Saito, et al.

It is certified that an error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

On the title page, Item (86), the PCT No. information is incorrect. Item (86) should read:

-- (86) PCT No.:

PCT/JP2006/303523

§ 371 (c)(1),

(2), (4) Date: Apr. 6, 2006 --

Mailing address of sender:

OBLON, SPIVAK MCCLELLAND, MAIER & NEUSTADT, L.L.P. 1940 DUKE STREET ALEXANDRIA, VIRGINIA 22314 Tel. (703) 413-3000 Fax. (703) 413-2220 (OSMMN 07/09) Patent No. 7,592,641

No. of add'l copies @ .30 per page

